



Base fija 1P fusible NH4 1000A, para perno M16

Medidas del Fusible



| Dimension | RT36-4 |
|-----------|--------|
| a | 200 |
| b | 83 |
| c | 50 |
| e1 | 96 |
| e2 | 88 |
| f | 79 |
| g | 20 |
| m | 150 |
| n | 16 |
| o | 32 |

Medidas del Portafusible



| Dimension | RT36-4 |
|-----------|--------|
| a | 96 |
| b | 304 |
| c1 | 145 |
| c2 | 165 |
| d | 45 |
| e | 30 |
| g1 | 4 |
| g2 | 13 |
| i | 260 |
| m | 47.5 |
| s | M16 |
| u | 45 |